

	 CALIBRES NO. 29	CS08-19-C-029-E	A

Technical improvements Calibre Family 1150 (1151, 1152, 1154, 1164 etc.)

RATCHET WHEEL DRIVING WHEEL 722 1150 1482

Problem

There are two problems that have been observed on the *ratchet wheel driving wheel*:

1. *The pinion becomes loose because of a faulty riveting*
2. *The pinion teeth break apart*

Solution

In order to solve the above mentioned problems, the riveting as well as the strength of the pinion material have been improved.

Spare parts

The reference of the new *ratchet wheel driving wheel* remains unchanged. The old version has been removed from our stock. We recommend you replace your stock of old *ratchet wheel driving wheel* with the new version.

SPARE PARTS

722 1150 1482 New ratchet wheel driving wheel



Note! The improved version is available from date code 39/03 (week 39/2003).