Technical improvements Calibre family 861 (863, 1861, 1863, 1866 etc.)

STEM-BOLT FOR HAMMER 722 0861 1759

Problem

An increase of watches for repair due to broken *stem-bolt for hammer* on calibre family 861 has been noticed.

Solution

A new *stem-bolt for hammer* with modified shape and improved material has been designed.

Spare Parts

The reference of the new *stem-bolt for hammer* remains unchanged. The old version has been removed from our stock. We recommend you replace your stock of old *stem-bolt for hammer* with the new version.

SPARE PARTS

722 0861 1759 New stem-bolt for hammer



Note! The improved version is available from date code <u>35/03</u> (week 35/2003).